

LIST OF COMPLETED PROJECTS

S/N	PROJECT TITLE	LOCATION	DATE
1.	ASSESSMENT & INSTALLATION OF HDPE TITE LINER ACROSS 12" X 300M HDD GAS PIPELINE	COCONUT RIVER APAPA	APRIL, 2017
2.	IN-LINE INSPECTION FOR PROPOSED UPGRADE OF 12"X 400M HDD GAS PIPELINE ALONG LIVERPOOL CROSSING	COCONUT RIVER APAPA	JULY, 2017
3.	PROCUREMENT AND SUPPLY OF VARIOUS ITEMS FOR PROJECT DEVELOPMENT DU DEVELOPMENT SUBSEA BONGA FPSO	VARIOUS	JUNE, 2017
4.	SWAMP FLOWLINES CONSTRUCTION AND MECHANICAL REPAIRS OPUKUSHI F/S WELL	OPUKUSHI	MAR, 2018
5.	PROCUREMENT AND SUPPLY OF SURFACE PREPARATION KIT FOR PIPELINE REPAIRS	VARIOUS	JUNE, 2018
6.	LEAK REPAIR BY CLAMPING ON THE 16" T/L (FID - 2434741)	ETEKURU	AUG, 2019
7	LEAK REPAIR BY SCREW CAPPING 14" (FID - 2452330 / 2452344)	UKPEILEDE	SEP, 2019
8.	IC REMOVAL / REPAIR ON THE 8" D/L (FID - 2180933)	UMUECHEM	SEP, 2019
9.	LEAK REPAIR/IC REMOVAL ON THE 14" (FID - 2452330 /2452344)	UKPEILEDE	SEP, 2019
10.	POST IP DEFECT REPAIR BY SPLIT SLEEVE IN-SERVICE WELDING 36" - PT - 13503.04	IRIEBE	SEP, 2019
11.	PIPELINE COATING REPAIR ON 28" TNP - KP 29.0,KP29.1,KP 29.3, KP29.4 29405.2M	NPOKU – BOMU	SEP, 2019
12.	PIPELINE COATING REPAIR ON 28" TNP - KP 28.60,KP28.62,KP28.8,KP 28.9	NPOKU – BOMU	SEP, 2019
13.	PIPELINE COATING REPAIR ON 28" TNP - KP 16.80,KP 16.8, KP 17.0	NPOKU – BOMU	SEP, 2019
14.	PIPELINE COATING REPAIR ON 28" TNP - KP 20.5,KP 27.7,KP 33.1,KP 83.3	NPOKU – BOMU	SEP, 2019
15.	PIPELINE COATING REPAIR ON 28" TNP - KP 23.4, KP 27.5, KP 28.0 KP 28.1	NPOKU – BOMU	SEP, 2019
16.	PIPELINE COATING REPAIR ON 28" TNP - KP 15.5, KP 15.6, KP 15.6, KP 16.8	NPOKU – BOMU	SEP, 2019
17.	PIPELINE COATING REPAIR ON 28" TNP - KP 15.5, KP 15.6, KP 15.6 KP, KP 16.8	NPOKU – BOMU	SEP, 2019
18.	LEAK REPAIR/ IC REMOVAL ON THE NEW 20" KOLO CREEK – RUMUEKPE T/L	OKOMAI	SEP, 2019
19.	LEAK REPAIR BY BLIND FLANGE INSTALLATION ON THE 28" TNP (FID – 2443760)	EJAMA EBUBU	SEP, 2019
20.	SPLIT TEE SLEEVING BY IN SERVICE WELDING ON THE 28" TNP (FID – 2443760)	EJAMA EBUBU	SEP, 2019
21.	POST IP DEFECT REPAIR BY SPLIT SLEEVE IN-SERVICE WELDING ON THE 36"	ENEKA	SEP, 2019
22.	LEAK REPAIR BY CLAMPING ON THE 14" OKORDIA (FID – 2475895)	IKARAMA	OCT, 2019
23.	LEAK REPAIR/IC REMOVAL ON THE 14" OKORDIA (FID – 2471501)	IKATA (PT 1)	OCT, 2019
24.	LEAK REPAIR/IC REMOVAL ON THE 14" OKORDIA (FID – 2473423)	IKATA (PT 2)	OCT, 2019
25.	LEAK REPAIR/IC REMOVAL ON THE 14" OKORDIA (FID – 2488941)	OSHIE	OCT, 2019
26.	REHABILITATION OF OBELLE WELL 5	OBELLE	OCT, 2019
27.	CROSSOVER INVESTIGATION & JIV ON 24" TNP (FID - 2432620/2474412)	MOGHO/KPOR	OCT, 2019
28.	BLIND FLANGING OF THE IC VALVE ON THE 24"/28" TNP (FID - 2474413/2432620)	KPOR	OCT, 2019
29.	LEAK REPAIR/IC REMOVAL ON THE 14" OKORDIA (FID – 2478772)	IHUOWO	OCT, 2019
30.	IC REMOVAL & REPAIR ON THE 24" TNP (FID – 2474413)	KPOR	OCT, 2019
31.	INSTALLATION OF WELD NECK FLANGES & VALVES (PTW – 3141 & 3148)	UBIE/UKPELEDE	OCT, 2019
32.	LEAK REPAIR/ IC REMOVAL BY IN-SERVICE (SLITE-TEE) WELDING 24" TNP (FID – 2452373)	PATRICK WATERSIDE	OCT, 2019
33.	IC REMOVAL ON THE 14" T/L (FID – 2498280)	ULA – OKOBO	NOV, 2019
34.	REHABILITATION OF UMUECHEM ROAD	UMUECHEM	NOV, 2019
35.	LEAK REPAIR/IC REMOVAL ON THE 24" TNP (FID – 2505132)	KPITE	NOV, 2019
36.	LEAK REPAIR BY CLAMPING ON THE 14" OKORDIA (FID - 2512915/2512912)	ULA – OKOBO	NOV, 2019
37.	LEAK REPAIR BY CLAMPING ON 18" ASSA (FID – 2531864)	AWARA	DEC, 2019
38.	LEAK REPAIR/ IC REMOVAL ON NEW 20" KOLO CREEK – RUMUEKPE T/L (FID – 2533005)	OKPOROWO	DEC, 2019
39.	SPLIT TEE INSTALLATION BY IN-SERVICE WELDING ON 28" TNP - (FID – 2474412)	KPOR	DEC, 2019
40.	POST IP DEFECT REPAIR ON 24" – COFFERDAM CONSTRUCTION - (32616.77M)	PATRICK WATERSIDE	JAN, 2020
41.	POST IP DEFECT REPAIR ON 24" – COFFERDAM CONSTRUCTION (32023.64M)	PATRICK WATERSIDE	JAN, 2020
42.	POST IP DEFECT REPAIR ON 24" – COFFERDAM CONSTRUCTION (31486.79M – 1490.11M)	PATRICK WATERSIDE	JAN, 2020
43.	LEAK REPAIR BY CLAMPING ON 12" IMO RIVER T/L (FID - 2552145)	OGHALE	JAN, 2020
44.	LEAK REPAIR BY CLAMPING ON 20" TEP (FID - 2517785)	OTUMARA	JAN, 2020
45.	REPAIR BY SECTIONAL REPLACEMENT ON 8" ELBOW	OUTMARA F/S	JAN, 2020
46.	SPLIT TEE INSTALLATION BY IN-SERVICE WELDING ON THE 20" TEP (FID -2452373)	OTUMARA	JAN, 2020
47.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 8" (2500.0M – 2586.1M)	UBIE D/L	JAN, 2020
48.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 8" (2790.0M – 2803.0M)	UBIE D/L	JAN, 2020
49.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 8" (2238.7M – 2420.0M)	UBIE D/L	JAN, 2020
50.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 8" (1247.7M – 1432.9M)	UBIE D/L	JAN, 2020
51.	LEAK REPAIR / JIV ON THE 20" KCTL	RUMUEKPE	FEB, 2020
52.	REPAIR BY SECTIONAL REPLACEMENT ON THE 8"	OTUMARA	FEB, 2020
53.	JIV/BLIND FLANG INSTALLATION ON 14" (FID - 2571635)	ABUA	FEB, 2020
54.	JIV/LEAK REPAIR BY CLAMPING ON 28" TNP (FID - 2611470)	RUMUEWHARA	MAR, 2020
55.	JIV/LEAK REPAIR BY CLAMPING ON 28" TNP (FID - 2611431)	ETEO	MAR, 2020
56.	JIV/LEAK REPAIR BY CLAMPING ON 12" (FID - 2605522)	ETEO	MAR, 2020
57.	ADDITIONAL SUPPORT SPREAD ON THE 24"	OGBOTOBO	MAR, 2020
58.	JIV/LEAK REPAIR ON THE 12" OGUTA – EGBEMA TL (FID - 2605522)	EZIORSU	MAR, 2020
59.	LEAK REPAIR BY CLAMPING ON THE 16" ASSA – EGBEMA (FID - 2613155)	UMUDIKE	MAR, 2020

60.	POST IP DEFECT BY SECTIONAL REPLACEMENT 24" TRP	OGBOTOBO	MAR, 2020
61.	SPLIT TEE INSTALLATION BY IN-SERVICE WELDING ON 24" KP 19 (FID - 2585998)	AGHORO KP 29	MAR, 2020
62.	POST IP DEFECT BY EXCAVATION 24" TRP KP 29 (FID - 2571635)	AGHORO KP 29	MAR, 2020
63.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 24" TRP KP 10.0 (FID - 11834)	OGBOTOBO	MAR, 2020
64.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 24" TRP KP 10.3 (FID - 11512)	OGBOTOBO	MAR, 2020
65.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 24" TRP KP 11.6 12104,14455,14946,17349	OGBOTOBO	MAR, 2020
66.	IP DEFECT REPAIR BY SECTIONAL REPLACEMENT 24" TRP KP 12.8 (FID - 11512)	OGBOTOBO	MAR, 2020
67.	JIV/LEAK REPAIR BY CLAMPING ON 10" DIEBU CREEK – NUN RIVER (FID - 2624644)	OSOKAMA	APR, 2020
68.	JIV/LEAK REPAIR BY CLAMPING ON 14" OKORDIA – RUMUEKPE TL (FID - 2616750)	AKINIMA	APR, 2020
69.	LEAK REPAIR/ IC REMOVAL 14" OKORDIA – RUMUEKPE TL (FID - 2625566)	IHUOWO	APR, 2020
70.	LEAK REPAIR BY CLAMPING ON 14" OKORDIA – RUMUEKPE TL (FID - 2631887)	EDOHA	APR, 2020
71.	LEAK REPAIR BY CLAMPING ON 18" ASSA - EGBEMA (FID - 2625819)	AWARA	APR, 2020
72.	LEAK REPAIR BY CLAMPING ON 18" ASSA - EGBEMA (FID - 2624325)	AWARA	APR, 2020
73.	LEAK REPAIR BY CLAMPING ON 14" OKORDIA – RUMUEKPE TL (FID - 2626666)	IKARAMA	APR, 2020
74.	LEAK REPAIR/ IC REMOVAL ON THE 14" OKORDIA - EGBEMA (FID - 2626666)	OSHIKA	APR, 2020
75.	LEAK REPAIR/ IC REMOVAL BY SECTIONAL REPLACEMENT ON THE 8" (1760M, 1471M)	UBIE	APR, 2020
76.	LEAK REPAIR (NEW) BLINDING ON THE 20" KCTL (FID - 2446482)	OKPOROWO	MAY,2020
77.	LEAK REPAIR (OLD) BLINDING ON THE 20" KCTL (FID - 2446482)	OKPOROWO	MAY,2020
78.	JIV/LEAK REPAIR BY CLAMPING ON THE 16" (FID - 2638020/ 2639827)	ETEKURU	MAY,2020
79.	JIV/LEAK REPAIR BY CLAMPING ON THE 16" (FID - 12700)	OPOROMA	MAY,2020
80.	STRINGING, SURFACE WELDING & LOWERING 16" (19571)	OPOROMA	MAY,2020
81.	DEFECT VERIFICATION & REPAIR BY SLEEVING ON THE 16" (154.29m)	OPOROMA	MAY,2020
82.	LEAK REPAIR BY CLAMPING ON THE 14" (FID - 2638015 - 4DAYS)	EDEOHA	MAY,2020
83.	LEAK REPAIR BY CLAMPING ON THE 14" (FID - 2568816 - 2DAYS)	EDEOHA	MAY,2020
84.	LEAK REPAIR BY CLAMPING ON THE 14" (FID - 2568816 - 6DAYS)	EDEOHA	MAY,2020
85.	JIV/LEAK REPAIR BY BLIND FLANGING ON THE 28" (FID - 2637568)	ELELENWO	MAY,2020
86.	BLIND FLANGING OF ILLEGAL BUCKERING POINT ON THE 20" (FID - 2412401)	ABUA	JUNE,2020
87.	LEAK REPAIR BY CLAMPING ON THE 20"	RUMUEKPE	JUNE,2020
88.	LEAK REPAIR BY CLAMPING ON THE 28" (FID - 2662361)	KPOR	JUNE,2020
89.	RESTRICTION REMOVAL BY SECTIONAL REPLACEMENT TRP KP 29 24" (FID - 0023234)	AGHORO KP29	JUNE,2020
90.	LEAK REPAIR BY SPLIT TEE INSTALLATION ON THE 28" TNP (FID - 2637568)	ELELEWO	JUNE,2020
91.	LEAK REPAIR BY CLAMPING ON THE 28" (FID - 2660117)	RUMUOHWA	JUNE,2020
92.	POST IP DEFECT BY SECT REP ON 14" (CRW 1)(257.43M - 283.64, 580.2M - 598.32M,888.07M-916.66M)	IKARAMA	JUNE,2020
93.	POST IP DEFECT BY SECT REP "ON THE 14" (CREW 2) FAILED PT 2 (PP LD - 1059M ACTUAL LD - 1045M)	IKARAMA	JUNE,2020
94.	POST IP DEFECT BY SECT REP "ON THE 14" SECT REP FAILED PT 1 (PP LD 116M ACTUAL LD 102M)	IKARAMA	JUNE,2020
95.	RESTRICTION REMOVAL BY SECTIONAL REPLACEMENT II TRP KP 29 24" (FID - 0023234 , 0027400)	AGHORO KP29	JULY,2020
96.	LEAK REPAIR / IC REMOVAL BY CLAMPING ON THE 8" (FID - 2685062)	ODAGWA	JULY,2020
97.	JIV/LEAK REPAIR BY CLAMPING ON THE 18" (FID - 2681377)	EGBEDA	JULY,2020
98.	JIV/LEAK REPAIR BY CLAMPING ON THE 18" (FID - 2684795)	AWARA	JULY,2020
99.	JIV/LEAK REPAIR BY CLAMPING ON THE 12" (FID - 2684795)	OPUOMA	JULY,2020
100.	LEAK REPAIR BY CLAMP WELDING ON THE 20" (FID - 2665340)	IMIRINGI	JULY,2020
101.	POST IP DEFECT REPAIR ON THE 24" PATRICK WATERSIDE (LD – 34521.628M)	PATRICK W/S	AUG,2020
102.	JIV / NON LEAK REPAIR BY CLAMPING ON THE 20" (FID - 2540796)	ISIOKPO	AUG2020
103.	JIV / NON LEAK REPAIR BY CLAMPING ON THE 36" (FID - 2541032)	ISIOKPO	AUG2020
104.	JIV / REPAIR BY CLAMPING ON THE 12" (FID - 2714325)	OWAZA	AUG,2020
105.	JIV/LEAK REPAIR BY CLAMPING ON THE 12" (FID - 2725259)	ODAGWA	SEPT,2020
106.	LEAK REPAIR BY CLAMPING ON THE 8" (FID - 2728324)	IGWURUTA	SEPT,2020
107.	LEAK REPAIR BY SECTIONAL REPLACEMENT II ON THE 8" (FID - 2728324)	IGWURUTA	SEPT,2020
108.	LEAK REPAIR BY CLAMPING ON THE 12 IMO RIVER (FID – 2781593)	UMULOLO	NOV,2020
109.	LEAK REPAIR BY CLAMPING ON THE 12 OGALE – OKOHIA (FID – 2781793)	OKOHIA	NOV,2020
110.	LEAK REPAIR BY CLAMPING ON THE 16 NUN RIVER – KOLO CREEK TL (FID - 2785801)	OTUGUE	NOV,2020
111.	VALVE CHANGE OUT AT EGBEMA MANIFOLD	EGBEMA	JAN,2021
112.	IC REMOVAL/ REPAIR BY CLAMPING ON THE 12" OGUTA- EGBEMA TL	EZORSU	JAN,2021
113.	LEAK REPAIR BY CLAMPING ON THE 12" OGUTA- EGBEMA TL	OPUOMA	JAN, 2021
114.	DEFECT REPAIR BY SECTIONAL REPLACEMENT ON THE 12" OGUTA- EGBEMA TL	UKWUGBA	JAN, 2021
115.	LEAK REPAIR BY CLAMPING ON THE 18" ASSA- EGBEMA TL	OCHIA	JAN, 2021
116.	POST IP DEFECT REPAIR BY SECTIONAL REPLACEMENT ON THE 24"TRP [KP 26.9 & 27]	AGHORO	JAN, 2021